



MS-710 ANTI-FOG UV PROTECTIVE GLASSES

Anti-Scratch Anti-Fog UV 400 Resistant

Complies with ANSI Z87.1-2003, GB14866-2006

FOR YOUR PROTECTION, READ THESE INSTRUCTIONS COMPLETELY BEFORE USING THIS SAFETY SPECTACLE.

- Spectacles DO NOT provide unlimited eye and face protection.
- Use this spectacle only for eye protection against light impact hazards such as small metal or wood chips, sparks and other small particles. Use proper shade of impact resistant filter lenses or plates for gas welding and cutting operations.
- This spectacle and lens are not unbreakable. They will not protect against severe impact hazards, such as (but not limited to) fragmenting grinding wheels, or abrasive discs, explosive devices, corrosive liquids or molten metal. Machine guards or other devices must be used where these hazards exist.
- Do not use this spectacle for protection against injurious rays from arc welding.
- Do not use this spectacle for laser operations unless it is clearly marked for this purpose.
- Inspect frequently and replace worn or damaged parts.
- Clean only with mild soap and lukewarm water, do not use solvents.
- PROTECT YOUR EYES, Misuse or abuse of this spectacle could result in serious eye Injury, up to and including blindness

MS-710 防霧防紫外線護目鏡

防刮 防霧 抗 UV 400 紫外線

符合 ANSI Z87.1-2003, GB14866-2006 檢驗標準

為了保護您的眼睛，使用本產品前請先閱讀以下說明：

- 眼鏡並無法提供無限的眼睛和面部防護，請小心使用。

- 使用這款眼鏡不僅能保護眼睛對光線的危險，也能阻擋如金屬或木屑，火花等小顆粒的侵入；再進行焊接和切割工作時，請使用適當的耐衝擊濾光鏡或氣體保護護目鏡，提供適當遮蔽防護。
- 這款眼鏡的鏡片與鏡架並非牢不可破。當有噴濺藥品或飛射物體或嚴重衝擊的危險時，例如砂輪，研磨盤，腐蝕性液體或熔融金屬或可能有爆炸危險的反應時，應戴護目鏡及護臉罩，必要時使用安全遮板。目前的機械設備或各種儀器不斷日新月異，請使用適當護具及護目鏡保護眼睛。
- 有害光線若來自其他弧面射入，這款護目鏡無法提供保護。
- 請不要使用這個護目鏡進行激光操作，除非它被明確標註可用於此用途。
- 請經常檢查鏡片，當有磨損或破壞的零部件請立即更換。
- 只用溫和肥皂和溫水清洗，不要使用溶劑。
- 保護您的眼睛，誤用或濫用都可能會導致嚴重的眼部損傷，甚至包括失明，請詳加注意

MS-710 防霧防紫外線護目鏡

防刮 防霧 抗UV 400 紫外線

符合 ANSI Z87.1-2003, GB14866-2006 檢驗標準

為了保護您的眼睛，使用本產品前請先閱讀以下說明：

- 眼鏡並無法提供無限的眼睛和面部防護，請小心使用。
- 使用這款眼鏡不僅能保護眼睛對光線的危險，也能阻擋如金屬或木屑，火花等小顆粒的侵入；再進行焊接和切割工作時，請使用適當的耐衝擊濾光鏡或氣體保護護目鏡，提供適當遮蔽防護。
- 這款眼鏡的鏡片與鏡架並非牢不可破。當有噴濺藥品或飛射物體或嚴重衝擊的危險時，例如砂輪，研磨盤，腐蝕性液體或熔融金屬或可能有爆炸危險的反應時，應戴護目鏡及護臉罩，必要時使用安全遮板。目前的機械設備或各種儀器不斷日新月異，請使用適當護具及護目鏡保護眼睛。
- 有害光線若來自其它弧面射入，這款護目鏡無法提供保護。
- 請不要使用這個護目鏡進行激光操作，除非它被明確標註可用於此用途。
- 請經常檢查鏡片，當有磨損或破壞的零部件請立即更換。
- 只用溫和肥皂和溫水清洗，不要使用溶劑。
- 保護您的眼睛，誤用或濫用都可能會導致嚴重的眼部損傷，甚至包括失明，請詳加注意

寶工實業股份有限公司
PROKIT'S INDUSTRIES CO., LTD.
<http://www.prokits.com.tw>
 E-mail: pk@mail.prokits.com.tw

